

Fig. 2





Fig. 3






Fig. 5




Fig. 6

(A)

S1	
POSITION OF REF. POINT	X1, Y1
CORRECTION ANGLE 0	- 0.1 DEG.
NUMBER OF SX	3
GAP BETWEEN SX	15mm
NUMBER OF SY	1
GAP BETWEEN SY	7mm

(B)

\$2	
POSITION OF REF. POINT	X2, Y2
CORRECTION ANGLE θ	- 0.2 DEG.
NUMBER OF SX	3
GAP BETWEEN SX	15mm
NUMBER OF SY	1
GAP BETWEEN SY	7mm

(C)

S3	
POSITION OF REF. POINT	X3, Y3
CORRECTION ANGLE 0	- 0.3 DEG.
NUMBER OF SX	3
GAP BETWEEN SX	15mm
NUMBER OF SY	1
GAP BETWEEN SY	7mm

Fig. 7

ľ

(A)

S1		
CPS	COORDINATE	
S1 - 1	x1,	y1
S1 - 2	x1,	y1 + 15
S1 - 3	x1,	y1 + 30
S1 - 4	x1,	y1 + 45
S1 – 5	$\times 1 + 7$,	y1
S1 – 6	×1 + 7,	y1 + 15
S1 - 7	x1 + 7,	y1 + 30
S1 – 8	$\times 1 + 7$,	y1 + 45

(B)

\$2		
CPS	COORDINATE	
S2 - 1	x2,	y2
S2 - 2	x2,	y2 + 15
S2 - 3	x2,	y2 + 30
S2 - 4	x2,	y2 + 45
S2 - 5	x2 + 7,	y2
S2 - 6	x2 + 7,	y2 + 15
S2 - 7	x2 + 7,	y2 + 30
S2 - 8	x2 + 7,	y2 + 45

(C)

S3		
CPS	COORDINATE	
S3 - 1	x3,	у3
S3 - 2	x3,	y3 + 15
S3 - 3	x3,	y3 + 30
S3 - 4	x3,	y3 + 45
S3 – 5	x3 + 7,	у3
S3 – 6	x3 + 7,	y3 + 15
s3 - 7	x3 + 7,	y3 + 30
S3 – 8	x3 + 7,	y3 + 45